



## Bangladesh University of Engineering and Technology Department of Mechanical Engineering

## Assignment-1 ME 260 – SOLIDWORKS


## Draw the isometric view of the pin support as shown below. Put the top, front and LS View on a drawing sheet.



Draw the isometric view of the guide bracket as shown below. Put the top, front and RS View on a drawing sheet.



## Draw the isometric view of the switch plate as shown below. Put the top, front and RS View on a drawing sheet.



Partha Kumar Das/ Lecturer, ME, BUET